







AUTEL®






Web: www.autel.com
Email: sales@autel.com








MaxiSys MS919S2

Packing List

Main Unit	
MaxiFlash VCMI2	
USB Type-C Cable	
Main Cable V2.0	
USB 2.0 Cable V2	
AC/DC Adapter (12 V)	
Auxiliary Power Outlet Adapter	
Spare Fuse 6x30mm 2 PCS	
Clamp Cable	
Attenuator 20:1 2 PCS	

Scope Test Lead 1x4 PCS	
Multimeter Test Lead 1x2 PCS	
Secondary Ignition Pickup 2 PCS	
Breakout Lead 4x6 PCS	
Multimeter Probe 1x2 PCS	
Flexible Back-pinning Probe 2x2 PCS	
Back-pinning Probe - Red/Green/ Blue/Yellow/Black 1x5 PCS	
Back-pinning Probe Screw 2 PCS	
Back-pinning Probe Replacement Needle 20 PCS	
Small Alligator Clip 2x2 PCS	

Large Dolphin Clip 1x2 PCS	
USB to Ethernet Adapter	
Quick Reference Guide	
Quick Start Guide	
Packing List (This document)	
Soft Cloth	
Tool Box	
Accessory Storage Bag	
Carrying Case	

*Oscilloscope Accessory Kit and Non-OBD II Adapter Kit, each sold separately.

WWW.OBD2.MX